SECURE CAP OF BOTTLE (1) WITH TAPE (2) AS SHOWN

ENLARGED VIEW

PLACE BOTTLE IN BAG (3)

TWIST BAG AND SECURE WITH TAPE (2)

FOLD OVER EXCESS BAG AND SECURE WITH TAPE (2)

PLACE LINER INTO BOX AND FILL WITH 2.25" DEEP LAYER OF ABSORBENT

REINFORCE BOX GIRTHWISE AND LENGTHWISE WITH TAPE (2) AS SHOWN, IS RECOMMENDED BUT NOT REQUIRED

SECURE SEAMS AND EDGES OF BOX WITH 7 STRIPS OF TAPE (6) AS SHOWN

FOLD LINER AND SECURE WITH TAPE (6)

POSITION BOTTLE IN CENTER OF BOX WITH SPACING EQUAL, THEN FILL BOX TO TOP WITH COMPRESSED ABSORBENT (5)

ENLARGED TOP VIEW

ITEM	DESCRIPTION	03F019
1	4 LITER, GLASS, ROUND, SCREW CAP BOTTLE WITH HANDLE, QTY. 1	
2	1-INCH WIDE, PRESSURE-SENSITIVE TAPE, FILAMENT-REINFORCED, IAW ASTM D5330, TY II	
3	INDIVIDUAL PLASTIC BAG, 4-MIL POLYETHYLENE, 18 X 30 IN.	
4	FIBERBOARD BOX, ASTM D5118, STYLE RSC, GRADE V3c, NSN: 8115-00-417-9320, 14X14X18 IN.	
5	CELLULOSE FIBER ABSORBENT, OR VERMICULITE, A-A-52450, 31 LBS.	
6	2-INCH WIDE, PRESSURE-SENSITIVE TAPE, IAW ASTM D 5486, TY II, NSN: 7510-00-266-6715	
7	4 MIL POLYETHYLENE BOX LINER, 28 X36 IN.	

RN: DLA03F019